Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: GO-WEYRAUCH 157-97-1918H-1

Field Name: RAY Well File #: 21272

Date Incident:3/17/2015Time Incident:14:45Facility ID Number:County:WILLIAMSTwp: 157Rng: 97Sec: 19Qtr:

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:0.4 MileDistance Nearest Water Well:0.4 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels			3	barrels
Brine	3	Barrels			3	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/19/2016 Clean Up Concluded: 3/25/2015

Risk Evaluation:

The source of the release was secured immediately upon discovery, and a vacuum truck was dispatched to the location to begin recovery efforts.

Areal Extent:

Impacted area north of the location measures approximately 54 feet x 46 feet.

Potential Environmental Impacts:

The release occurred above ground, and there was no surface water observed in the immediate vicinity of the release location. A vacuum truck was dispatched to the location in order to recover as much of the released emulsion as practicable.

Action Taken or Planned:

A vacuum truck was dispatched to the location in order to recover as much of the released emulsion as practicable. The impacted soil will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 3/18/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow was not contained according to the report. Followup is necessary.

Date: 4/14/2015 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 4/14/2015, at 2:40 p.m. Release was off location to the north of well pad. Area has been scraped and material removed. Conductivity readings were taken and show 1-2 ms/cm. No remaining impacts seen at this time. No further followup required.

Date: 7/13/2016 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 7/13/2016, at 9:40 a.m. Area to the north has a planted crop which is growing with no signs of distress noticed. No further follow-up is required.